

JOHN DEERE SNOOT BOOT

MOUNTING INSTRUCTIONS

PRODUCT DESCRIPTION

Highly visible boot that easily slides over your existing John Deere point designed with a smooth surface aiding in trash build up and high friction material ensuring in a long lasting product that will be on your corn head for years to come.

1. Always be sure header is in lock or safe position before working under header.
2. Remove front bolt from casting tip.
3. Slightly bend up top elongated washer.
4. Slide snoot boot over the casting tip underneath the elongated washer until the snoot boot is snapped over the bottom of the casting. A rubber mallet may be required.
5. Re install the front bolt back into the casting to hold the snoot boot. Do not over tighten the front bolt this could cause the snoot boot to bend damaging the part.



MAY WES
Original Poly People
A DIVISION OF PRIDE SOLUTIONS

120 Eastgate Drive SE
PO Box 7
Hutchinson, MN 55350

WWW.MAYWES.COM

1-800-788-6483
1-320-587-2322
1-320-587-6112 (Fax)